

## RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080169-7

2951 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 4-19-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DRAWN OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUT OUT CODE NO.	ACCT. OR W.O. NO.	S.O. NO.
322		44		23					

CHARGE TO  
QUANTITY  
RECEIVED

DRAWING NO. AND DESCRIPTION

QUANTITY  
ACCEPTED REJECTED

REMARKS

2 732644 Plate Mounting 2 No Stamps

INQ #5238

RECEIVED BY  
HMC-1968

INSPECTED BY

DATE 4-19-57

REJECTS RETURNED  
ON SHIP MEMO NO.RECEIVING INSPECTION REPORT  
HYCON MFG. COMPANY  
2951 E. COLORADO ST., PASADENA, CALIF.

No. 11995

RECEIVED FROM

DATE REC'D. 4-23-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DRAWN OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUT OUT CODE NO.	ACCT. OR W.O. NO.	S.O. NO.
322	0	30	0	23		63			

CHARGE TO  
QUANTITY  
RECEIVED

DRAWING NO. AND DESCRIPTION

QUANTITY  
ACCEPTED REJECTED

REMARKS

16 732602 3 Roller Assembly

INQ #5221

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080169-7

RECEIVED BY  
HMC-1968

INSPECTED BY

DATE

REJECTS RETURNED  
ON SHIP MEMO NO.